

FIG.1
RELATED ART





ON OFF OFF OFF OFF ON OPF OFF OFF Gray Level Number: 7 SE sub-fields SF9 ON ON OFF 32 ON ON OFF 32 32 SF632 SF5 16 Gray Level Number: 64 SW sub-fields SF4 ∞ SF3 SF2 SF1 sub-field Weighting / Value 1

Total Gray Level Number: 64x7=448

	<u></u>	32	SF12	NO	OFF	OFF	OFF	OFF	OFF	OFF	OFF)			
SE sub-fields		32	SF11	NO	NO	OFF	OFF	OFF	OFF	OFF	OFF			,	
		32	SF10	N O	NO	NO O	OFF	OFF	OFF	OFF	OFF		mher . 8		
		32	SF9	NO	NO	NO	NO	OFF	OFF	OFF	OFF	\ /	Gray Level Number: 8		
		32	SF8	N O	NO	NO O	NO O	NO	OFF	OFF	OFF			G ay r	
		32	SF7	NO	NO	NO	NO	N O	NO	OFF	OFF				
		35	SF6	NO	NO	N O	NO O	NO	N O	NO	OFF	J			
SW sub-fields	(16	SF5												
		∞	SF4			Grav Level Number: 32									
	{	4	SF3												
		2	2 SF2			ray Leve									
	_		SF1			Ċ	5								
elj–dis	Woight:	Value													

Total Gray Level Number :32x8=256

